
## **WisWAP Data Entry for Limited Weatherization Services** (9/10/2012)

- **1. BUILDING UNIT STATUS:** Prior to **Add Baseload Job**, select the appropriate Building Unit Status to report why the unit is not receiving treatment as a Regular Weatherization Job.
- 2. ADD BASELOAD JOB: Jobs for Limited Weatherization Services must be reported in WisWAP as a Baseload Job.



**3. ADD NEW MEASURE:** When the job type is Baseload Job, only Categories and Measures approved for Limited Weatherization Services will be available for selection.



**4. REPORTS:** Select WisWAP Reports (Building Unit Counts, Average Cost per Measure, and Measure Cost Detail) include a search parameter that limits data returned by Job Kind.



**5. ADD REGULAR JOB:** If a unit is later selected to receive full weatherization, update the Unit Status, and report measures for full weatherization under Regular Job.



## **Baseload Measures Active in WisWAP**

- BLPCFL	Baseload Lighting							Add Measure
BLPCFL005	CFL Bulb	each	SFH,MHT,2TO4,AMUB	PB,EAP	Yes	No	No	
BLPCFL010	Halogen Torchiere Replacement	each	SFH,MHT,2TO4,AMUB	EAP,PB	Yes	No	No	
BLPCFL015	LED Exit Light	each	2TO4,AMUB	PB,EAP	Yes	No	No	
BLPCFL020	Exterior	each	SFH,MHT,2TO4,AMUB	PB,EAP	Yes	No	No	
BLPCFL025	CFL 3-Way Bulb	each	SFH,MHT,2TO4,AMUB	PB,EAP	Yes	No	No	

=	<u>BLURR</u>	Baseload Refrigerator							<u>Add Measure</u>
	BLURR005	Replacement	each	SFH,MHT,2TO4,AMUB	PB,EAP	Yes	No	No	
	BLURR010	Remove Additional Unit	each	SFH,MHT,2TO4,AMUB	PB,EAP	Yes	No	No	
Ξ	BLVFR	Baseload Freezer							Add Measure
=	BLVFR005	Baseload Freezer Replacement	each	SFH,MHT,2TO4,AMUB	PB,EAP	Yes	No	No	Add Measure